

SECRET

IDEA-0899

Copy 5 of 5

24 September 1962

MEMORANDUM FOR: Deputy Assistant Director, OSA-DD/R

SUBJECT : DC Generator Failures on U-2 Aircraft

DC Generators are standard Air Force equipment and are obtained by the [] from normal Air Force supply channels. As a result of [] complaint in [] 092 (attached) we have consulted with [] [] and [] and have requested the following actions:

- 25X1A a. [] to perform teardown inspection on the two faulty generators and submit findings and recommendations to this Headquarters.
- 25X1A b. [] to report apparent poor quality control to the prime USAF depot concerned and request corrective action.
- 25X1A c. [] to institute new SOP whereby LAC will pre-inspect all DC generators prior to issue.
- 25X1A d. [] to send all reparable DC generators to LAC for repair unless adequate quality control from prime USAF depot can be assured.

[]
Chief, Materiel Division
OSA-DD/R

25X1A

[] are
Dist: Cy 1 - Addressee
2 - AD/OSA
3 - OD/OSA
4 - MD/OSA
5 - RIB/OSA

NOT TO BE DISSEMINATED
OUTSIDE OSA-DD/R

SECRET